

LONG BEACH COMMUNITY COLLEGE DISTRICT
CONTRACTS MANAGEMENT DEPARTMENT
4901 EAST CARSON STREET
LONG BEACH, CA 90808
Ph. (562) 938-4947 | Fax: (562) 938-4544

BID C1815A DOOR HARDWARE REPLACEMENT
BUILDINGS CC, GG, HH, II, JJ, MM, A, T, AND LAC CDC PROJECT
AT THE
LIBERAL ARTS & PACIFIC COAST CAMPUSES

ADDENDUM NO. 1

May 10, 2018

This Addendum forms a part of the Contract Documents and modifies the original bid documents. Acknowledge receipt of the Addendum on Section 1.2 of the Bid Proposal. Failure to do so may result in the bid being deemed non-responsive.

Note: It is the responsibility of all bidders to notify all subcontractors from whom they request bids and from whom they accept bids of all changes contained in this addendum.

ADDENDUM NO. 1 CONTENTS

I. ANSWERS TO PREBID INQUIRIES

* * * * *

I. ANSWERS TO PRE BID INQUIRIES

1. Q: For Hardware set 37 (1). What does the 1 in parenthesis mean?

A: The (1) is an internal demarcation for LBCC use only. Contractor should include this Hardware Group 37 in their bid.

2. Q: Is MM118-1 the same as MM118 on floor plan?

A: Yes.

3. Q: Is MM124A-2 the same as MM124-2 on floor plan?

A: Yes.

4. Q: Is MM124A-3 the same as MM124-3 on floor plan?

A: Yes.

5. Q: MM120-3 is not on floor plan?

A: Contractor should include Door MM120-3 with hardware schedule 04 as listed on the Door Index in their bid. These pair of doors are located on the dividing wall of Room MM124.

6. Q: There are two MM110-2 doors listed on the door index?


A: The first door on the list that is marked MM110-2 (RHR) should have been listed as MM110-1 with Hardware Group 38, as this is an exterior door with an Omni lock.

7. Q: Is MM128 on floor plan MM128B-1?

A: Disregard all reference for Door MM128, MM 128A-1, and MM 128B-1 as these doors are not part of this project.

*****END OF ADDENDUM NO. 1*****

LONG BEACH COMMUNITY COLLEGE DISTRICT



Alan Moloney, Deputy Director
Purchasing & Contracts

5-10-18
Date